



Vehicle History Report™



2018 TOYOTA COROLLA L/LE/XLE/SE/XSE

VIN: 2T1BURHE7JC073603
 SEDAN 4 DR
 1.8L I4 F DOHC 16V
 GASOLINE
 FRONT WHEEL DRIVE



No accidents or damage reported to CARFAX



At least 1 open recall



3 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/9/20 at 8:35:13 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Title History

Summary

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed
No Problem

Not Actual Mileage | Exceeds Mechanical Limits



Guaranteed
No Problem



Additional History

Summary

Not all accidents / issues are reported to CARFAX

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

No structural damage reported to CARFAX.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.



No Issues Reported

Manufacturer Recall

At least 1 manufacturer recall requires service. Locate an authorized [Toyota dealer](#) near you to schedule an appointment. [View Toyota disclosure](#)

Recall Reported



Detailed History

Mileage	Source	Comments
03/05/2018	NICB	Vehicle manufactured and shipped to original dealer
01/13/2020	Toyota Motor Sales, USA, Inc.	<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #20V012 - Recall #20TA02 SAFETY RECALL 20TA02 (REMEDY NOTICE), MULTIPLE MODELS AND MODEL YEARS, VEHICLE - MAY STALL DURING DRIVING AT HIGHER SPEED - Status: Remedy Available <p>Locate an authorized Toyota dealer near you to schedule an appointment</p> <ul style="list-style-type: none"> - Learn more about this recall

Description: The subject vehicles are equipped with a low-pressure fuel pump which may stop operating. If this were to occur, warning lights and messages may be displayed on the instrument panel, and the engine may run rough. This may result in a vehicle stall, and the vehicle may be unable to be restarted.

If a vehicle stall occurs while driving at higher speeds, this could increase the risk of a crash.

Remedy: Any authorized Toyota dealer will replace the low-pressure fuel pump with an improved one FREE OF CHARGE.

01/17/2020

Toyota Motor Sales, USA, Inc.

Manufacturer Safety recall issued

- NHTSA #20V024
- Recall #20TA03 SAFETY RECALL 20TA03 (REMEDY
- NOTICE) - MULTIPLE MODELS AND MODEL YEARS
-
- INCOMPLETE OR NONDEPLOYMENT OF AIRBAGS AND/OR SEAT
- BELT PRETENSIONERS MAY OCCUR
- Status: Remedy Available

Locate an authorized Toyota dealer near you to schedule an appointment

- [Learn more about this recall](#)

Description: The subject vehicles are equipped with an electronic control unit (ECU) from a specific supplier that is designed to receive signals from crash sensors and deploy the airbags and seat belt pretensioners. The ECU may not have adequate protection against certain electrical noise that can occur in certain crashes, such as severe underride crashes. This can lead to incomplete or nondeployment of the airbags and/or seat belt pretensioners.

Airbags and seat belt pretensioners that do not deploy as intended can increase the risk of injury in a crash.

Remedy: Any authorized Toyota dealer will install a noise filter between the airbag control module and its wire harness FREE OF CHARGE.

Have Questions? Consumers, please visit our Help Center at www.carfax.eu



Glossary

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

Toyota Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013 . This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While TOYOTA provides data to Carfax Inc. on a regular basis, this report may not include very recent activity. For the manufacturer's most current information on recall/campaign activity for any Toyota, Lexus or Scion brand vehicle, you must go to <http://toyota.com/recall> or <http://lexus.com/recall>.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2020 CARFAX Europe GmbH, a unit of IHS Markit Ltd. All rights reserved.
11/9/20 8:35:13 AM (CST)